

Video Bios Release Notes

Coffee Lake, Kaby Lake Skylake and Amber Lake

Build# 1062

December 11, 2018

INTEL CONFIDENTIAL

INFORMATION IN THIS DOCUMENT IS PROVIDED IN CONNECTION WITH INTEL PRODUCTS. NO LICENSE, EXPRESS OR IMPLIED, BY ESTOPPEL OR OTHERWISE, TO ANY INTELLECTUAL PROPERTY RIGHTS IS GRANTED BY THIS DOCUMENT. EXCEPT AS PROVIDED IN INTEL'S TERMS AND CONDITIONS OF SALE FOR SUCH PRODUCTS, INTEL ASSUMES NO LIABILITY WHATSOEVER AND INTEL DISCLAIMS ANY EXPRESS OR IMPLIED WARRANTY, RELATING TO SALE AND/OR USE OF INTEL PRODUCTS INCLUDING LIABILITY OR WARRANTIES RELATING TO FITNESS FOR A PARTICULAR PURPOSE, MERCHANTABILITY, OR INFRINGEMENT OF ANY PATENT, COPYRIGHT OR OTHER INTELLECTUAL PROPERTY RIGHT.

UNLESS OTHERWISE AGREED IN WRITING BY INTEL, THE INTEL PRODUCTS ARE NOT DESIGNED NOR INTENDED FOR ANY APPLICATION IN WHICH THE FAILURE OF THE INTEL PRODUCT COULD CREATE A SITUATION WHERE PERSONAL INJURY OR DEATH MAY OCCUR.

Intel may make changes to specifications and product descriptions at any time, without notice. Designers must not rely on the absence or characteristics of any features or instructions marked "reserved" or "undefined." Intel reserves these for future definition and shall have no responsibility whatsoever for conflicts or incompatibilities arising from future changes to them. The information here is subject to change without notice. Do not finalize a design with this information.

This document contains information on products in the design phase of development.

The products described in this document may contain design defects or errors known as errata, which may cause the product to deviate from published specifications. Current characterized errata are available on request.

Contact your local Intel sales office or your distributor to obtain the latest specifications and before placing your product order.

Intel is a trademark of Intel Corporation in the U.S. and other countries.

*Other names and brands may be claimed as the property of others.
Copyright © 2018, Intel Corporation. All rights reserved.

Revision History

Date	Build Number	Description
December 11, 2018	1062	PV : SKL, KBL, CFL-KBP, AML
November 23, 2018	1061	PV : SKL, KBL, CFL-KBP, AML
September 3, 2018	1060	PV : SKL, KBL, CFL-KBP, AML
June 23, 2018	1059	PV : SKL, KBL, CFL-KBP, AML
June 6, 2018	1058	PV : SKL, KBL, CFL-KBP, AML
May 7, 2018	1056	PV : SKL, KBL, CFL-KBP, AML
April 6, 2018	1055	PV : SKL, KBL, CFL-KBP

Date	Build Number	Description
July 31, 2017	1054	PV : SKL, KBL, CFL-KBP
May 17,2017	1052	PV : SKL, KBL
March 12,2017	1051	PV : SKL, KBL
January 12,2017	1050	PV : SKL, KBL
November 24,2016	1049	PV : SKL, KBL
October 18,2016	1048	PV : SKL, KBL
October 3,2016	1047	PV : SKL, KBL
July 22, 2016	1046	PV : SKL, KBL
June 28, 2016	1045	PV : SKL, KBL

Video BIOS release contains support for the following Intel Chipsets/Processors:

- CFL-S+KBL PCH combination only
- 8th Gen Intel® Core™ processor family (codename Amber Lake)
- 7th Gen Intel® Core™ processor family (codename Kaby Lake)
- 6th Gen Intel® Core™ processor family (codename Skylake)

Change Logs

Change Logs			
DCN #	BUG/RCR	DCN Title	Version
1606833630	[NA]	Fix for DP monitor blink issue	1062
1606780035	[NA]	Addition of Device-Id 0x3E9C	1061
1606730719	[NA]	Link training programming optimization	1061
1606463219	[NA]	Add AML 4+2 device Id 0x87CA in ULX list	1060
1506659773	[NA]	Add device Id 87C0 for AML and move 591C from HALO list to ULX list	1060
1605787640	[NA]	New PCH ID Range addition	1060
1605327603	[NA]	Add disable partition clock gating WA as per GOP	1059
1605346099	[NA]	Porting Device ID changes in SKL Branch from CFL Branch	1059

1605276420	[NA]	When enable KVMR in VBIOS, system hang observed	1058
1506008693	[NA]	New Device ID addition for AML	1058
1505861738	[NA]	16-bit apps failing in DOS	1058
1505743652	[NA]	External Monitor cannot display in F10 setup / DOS / EFI environments after plug External monitor then close lid under "Legacy enable mode" in F10.	1058
1504782455	[NA]	Missing Device IDs VBIOS SKL	1058
1505589966	[NA]	HDMI Vswing levels not changing even if changed via VBT	1058
1505514771	[NA]	VBE "4F11, 01- Return Flat Panel Information" is causing "Unexpected single-step interrupt" error when "KVMR Session/Fake DVI Display Support" is set to "Enabled" and without eDP attached	1058
1604863996	[NA]	New device ID addition request for KBL PCH H3xx and KBL Graphics	1056
1504708623	[NA]	Switch monitor through inject 4K monitor can see the indistinct screen under the setup menu.	1055
1604414522	[NA]	Addition of KBL PCH DID.	1054
1604342269	[NA]	[SKL] EDIDLess EFP Support for embedded platform only	1052
1604302657	[NA]	HDMI clock Multiplier changes	1051
1604277361	[NA]	Update KBL device ID_s as per latest	1050
1604277818	[NA]	I2C Changes [SKL]	1050
1604255181	[NA]	No POST time message display	1049
1604250145	[NA]	Overflow Status fix for ACPI Timer delay routine	1049
1604244321	[NA]	Black screen hung 0xb2 with legacy mode(VBIOS) problem	1049
1604242973	[NA]	Display flicker after boot to OS.	1049
1604235742	[NA]	Moving Work Station SKUs Device IDs to Mobile Device IDs list	1048
1604237499	[NA]	[VBIOS] [SKL/KBL] Backlight Frequency Calculation changes	1048
1604238751	[NA]	[DG2_RS1] [Dell Pebble Creek DVT1]Black screen with legacy mode(VBIOS) problem	1048
1604232838	[NA]	SKL delay function changes based on ACPI Timer	1047
1604217409	[NA]	Add support for custom DP Vswing tables for short and long trace lengths	1047
1604203981	[NA]	Monitor will flash garbage when do lid close/open in DOS/UEFI/BIOS setup/Boot menu	1046
1604203870	[NA]	OEM Customizable Modes without dependency on DTD timings	1046

4187147	[NA]	Added support for new PCH Device IDs on Kabylake	1045
4186604	[NA]	Removed disable scrambling code before link training	1044
4166269	[NA]	System black screen & hang up "b2" code during running warm boot/cold boot stress test	1043
4166228	[NA]	Support for mailbox operation for eDP 1.4	1043
4165343	[NA]	Support for eDP1.4 functionality in VBIOS.	1042
4164068	[10032063]	System would stop to boot to Win7 32-bit with DP + DP to DVI converter	1040
4164011	[NA]	Added support to remove 48 Hz in Modes Removal Table in VBT	1040

Known Issues

None