

TEL : 82-53-668-0255
 FAX : 82-53-668-0277
 AFS : RKRRYNYX
 E-mail : aais@korea.kr
 Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
 11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 29/21
23 SEP 2021

GEN : NIL

ENR : NIL

A D : BUSAN/Gimhae INTL(RKPK)

UNSERVICEABILITY OF KMH TVOR/DME

1. INTRODUCTION

The TVOR/DME(KMH) at Gimhae INTL Airport will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 8 SEP 2021 To 1559 UTC 29 DEC 2021

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates	AIP Page
VOR/DME	KMH	113.8 MHz (CH 85X)	35°11'56.9"N 128°56'08.2"E (VOR) 35°11'56.8"N 128°56'07.7"E (DME)	RKPK AD 2-9

4. REMARKS

(1) During the replacement period, some flight procedures of RKPK will not be available as follows.

	RWY	Procedure	AIP Page
SID	36L/R	BEVSI 3	RKPK AD CHART 2-16
		SOORO 1	RKPK AD CHART 2-17
		ATLAX 2	RKPK AD CHART 2-18
	18L/R	ULSUK 3	RKPK AD CHART 2-20
		BAHDA 1	RKPK AD CHART 2-21
Instrument Approach	36L/R	VOR/DME RWY 36L/R	RKPK AD CHART 2-32, 2-38
	18L/R	VOR/DME - A	RKPK AD CHART 2-39

(2) During the replacement period, some flight procedures of RKPK will be available restrictively as follows.

Procedure	Segment	Restrictions	AIP Page
ILS Y RWY 36L/R LOC/DME Y RWY 36L/R	INITIAL	Radar vector	RKPK AD CHART 2-27, 2-28, 2-33, 2-34
	INTERMEDIATE, FINAL	As published	
	Missed approach procedure	As ATC instruction	

(3) Any change to the contents of this page will be notified by NOTAM.

(AIRAC AIP SUP 16/21 is hereby superseded)