

TEL : 82-53-668-0255
FAX : 82-53-668-0277
AFS : RKRYYNYX
E-mail : aais@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 18/21
26 AUG 2021

GEN : NIL

ENR : NIL

A D : YEOSU/Yeosu(RKJY)

UNSERVICEABILITY OF ILS/DME

1. INTRODUCTION

The ILS/DME for RWY 17 at Yeosu Airport will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 6 OCT 2021 To 1559 UTC 23 MAR 2022

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid, CAT of ILS/MLS	ID	Frequency	Position of Transmitting Antenna Coordinates
LOC 17	IYSO	111.5 MHz	34°49'52.0"N 127°37'21.9"E
GP 17	-	332.9 MHz	34°50'57.2"N 127°36'54.4"E
DME 17	IYSO	(T)1013.0 MHz (R)1076.0 MHz (CH 52X)	34°50'57.3"N 127°36'54.6"E

4. WORKING AREA

See the diagram.

5. REMARKS

(1) During the replacement period, some flight procedures of RKJY will not be available as follows.

	RWY	Procedure	AIP Page
Instrument Approach	17	ILS or LOC Y RWY 17	RKJY AD CHART 2-14
		ILS or LOC Z RWY 17	RKJY AD CHART 2-15

(2) These cranes do not penetrate any obstacle limitation surfaces of RKJY.

(3) Any change to the contents of these pages will be notified by NOTAM.

6. DIAGRAM

