

TEL : 82-32-880-0256
FAX : 82-32-889-5902
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 7/22
10 MAR 2022

GEN : NIL

ENR : NIL

A D : ULSAN/Ulsan(RKPU)

UNSERVICEABILITY OF ILS/DME

1. INTRODUCTION

The ILS/DME for RWY 36 at Ulsan Airport will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 20 APR 2022 To 1600 UTC 2 NOV 2022

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid, CAT of ILS/MLS	ID	Frequency	Position of Transmitting Antenna Coordinates
LOC 36	IULS	110.3 MHz	35°36'16.3"N 129°21'02.9"E
GP 36	-	335 MHz	35°35'13.8"N 129°21'12.1"E
DME 36	IULS	(T)1001 MHz (R)1064 MHz (CH 40X)	35°35'13.8"N 129°21'12.2"E

4. WORKING AREA

See the diagram.

5. REMARKS

(1) During the replacement period, some flight procedures of RKPU will not be available as follows.

	RWY	Procedure	AIP Page
Instrument Approach	36	ILS Y or LOC Y RWY 36	RKPU AD CHART 2-15
		ILS Z or LOC Z RWY 36	RKPU AD CHART 2-16

(2) Any change to the contents of these pages will be notified by another AIP SUP or NOTAM.

6. DIAGRAM

