

TEL : 82-32-880-0256
FAX : 82-32-889-5902
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 13/23
9 MAR 2023

GEN : NIL

ENR : NIL

A D : YEOSU/Yeosu(RKJY)

UNSERVICEABILITY OF ILS/DME

(Effective : 1600 UTC 19 APR 2023)

1. INTRODUCTION

The ILS/DME for RWY 35 at Yeosu Airport will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 19 APR 2023 To 1600 UTC 1 NOV 2023

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid, CAT of ILS/MLS	ID	Frequency	Position of Transmitting Antenna Coordinates
LOC 35	IYSU	109.7 MHz	34°51'13.0"N 127°36'42.2"E
GP 35	-	333.2 MHz	34°50'10.4"N 127°37'18.0"E
DME 35	IYSU	(TX)995.0 MHz (RX)1058.0 MHz (CH 34X)	34°50'10.5"N 127°37'18.1"E

4. WORKING AREA

See the below diagram.

5. REMARKS

(1) During the replacement period, some flight procedures of RKJY will not be available as follows.

	RWY	Procedure	AIP Page
Instrument Approach	35	ILS Y or LOC Y RWY 35	RKJY AD CHART 2-19
	35	ILS Z or LOC Z RWY 35	RKJY AD CHART 2-20

(2) These cranes do not penetrate any OBST limitation surfaces of RKJY.

(3) Any change to the contents of these pages will be notified by another AIP SUP or NOTAM.

6. DIAGRAM

