

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : https://aim.koca.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 54/25
29 MAY 2025

GEN : NIL

ENR : NIL

A D : MUAN/Muan INTL(RKJB)

UNSERVICEABILITY OF ILS/DME

(Effective : 1600UTC 9 JUL 2025)

1. INTRODUCTION

The ILS/DME for RWY 01 at Muan INTL Airport will be unserviceable due to RWY 01 LOC replacement WIP.

2. PERIOD

From 1600 UTC 21 FEB 2024 To 1500 UTC 2 OCT 2025

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates
GP 01	-	331.1 MHz	34°58'53.3"N 126°22'54.0"E
DME 01	IMUN	(TX)1 017 MHz (RX)1 080 MHz (CH 56X)	34°58'53.2"N 126°22'53.8"E
LOC 01		111.9 MHz	35°00'23.1"N 126°22'57.8"E

4. WORKING AREA

See the AIRAC AIP SUP 25/25(CONSTRUCTION WORK FOR RUNWAY EXTENSION).

5. REMARKS

(1) During the replacement period, some flight procedures of Muan INTL Airport will not be available as follows.

	RWY	Procedure	AIP Page
Instrument Approach	01	ILS Y or LOC Y RWY 01	RKJB AD CHART 2-14
	01	ILS Z or LOC Z RWY 01	RKJB AD CHART 2-15

(2) Any change to the contents of this page will be notified by NOTAM.

(AIRAC AIP SUP 26/25 is hereby superseded)