

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRYYNYX
E-mail : aisd@korea.kr
Web : https://aim.koca.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 78/25
21 AUG 2025

GEN : NIL

ENR : NIL

A D : MUAN/Muan INTL(RKJB)

UNSERVICEABILITY OF ILS/DME

(Effective : 1600UTC 1 OCT 2025)

1. INTRODUCTION

The ILS/DME for RWY 19 at Muan INTL Airport will be unserviceable due to RWY 19 ILS/DME replacement WIP.

2. PERIOD

From 1600 UTC 1 OCT 2025 To 1600 UTC 24 DEC 2025

3. RADIO NAVIGATION AND LANDING AIDS INFO

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates
GP 19	-	329.3 MHz	35°00'04.3"N 126°22'53.5"E
DME 19	IMAN	(TX) 987 MHz (RX) 1050 MHz (CH 26X)	35°00'04.3"N 126°22'53.3"E
LOC 19		108.9 MHz	34°58'35.0"N 126°22'58.5"E

4. WORKING AREA

See the diagram below.

5. REMARKS

(1) During the replacement period, some flight procedures of Muan INTL Airport will not be available as follows.

	RWY	Procedures	AIP Page
Instrument Approach	19	ILS Y or LOC Y RWY 19	RKJB AD CHART 2-18
	19	ILS Z or LOC Z RWY 19	RKJB AD CHART 2-19

(2) Any change to the contents of these pages will be notified by NOTAM.

(AIRAC AIP SUP 59/25 is hereby superseded)

6. DIAGRAM

