

TEL : 82-32-880-0256
FAX : 82-32-889-5905
AFS : RKRRYNYX
E-mail : aisd@molit.go.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 31/20
17 DEC 2020

GEN : NIL

ENR : NIL

A D : JEJU/Jeongseok(RKPD)

UNSERVICEABILITY OF ILS/DME

1. INTRODUCTION

The ILS/DME for RWY 01/19 at Jeongseok Aerodrome will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 4 DEC 2019 To 1600 UTC 19 MAY 2021

3. RADIO NAVIGATION AND LANDING AIDS INFO

Type of aid, CAT of ILS/MLS	ID	Frequency	Position of transmitting antenna coordinates
LOC 01	IJDG	108.3 Mhz	33°24'22.7"N 126°42'41.2"E
GP 01	-	334.1 Mhz	33°23'07.5"N 126°42'46.3"E
DME 01	-	981 Mhz (CH 20X)	33°23'07.8"N 126°42'46.5"E

4. WORKING AREA

See the diagram

5. REMARKS

(1) During the replacement period, some flight procedures of RKPD will not be available as follows.

	RWY	Procedure	AIP page
Instrument Approach	01	ILS RWY 01	RKPD AD CHART 2-13
		LOC RWY 01	RKPD AD CHART 2-14


(2) These cranes do not penetrate any obstacle limitation surfaces of RKPD.

(3) Any change to the contents of these pages will be notified by NOTAM.

(AIP SUP 10/20 is hereby superseded)

6. DIAGRAM

WORK POINT OF
CONSTRUCTION



NOT TO SCALE