TEL: 82-53-668-0255 FAX: 82-53-668-0277

AFS: RKRRYNYX
E-mail: aais@korea.kr
Web: http://ais.casa.go.kr

REPUBLIC OF KOREA

Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC AIP

Supplement 9/21

6 MAY 2021

GEN: NIL

ENR: NIL

A D: SEOUL/Gimpo INTL(RKSS)

OPERATIONAL RESTRICTIONS

1. INTRODUCTION


The ALS(Approach lighting systems) for RWY 14L at Gimpo INTL Airport will be unserviceable due to replacement.

2. PERIOD

From 1400 UTC 1 JUL 2021 To 1500 UTC 31 OCT 2021

3. WORKING AREA (See the diagram below)

A distance of construction is 900 m from the RWY 14L threshold.



4. REMARKS

- (1) ALS for RWY 14L unserviceable all period From 1400 UTC 1 JUL 2021 To 1500 UTC 31 OCT 2021 irrespective of working hours.
- (2) During the period, landing weather minima changed as [AIP RKSS AD CHART 2-26, 2-27, 2-28].
- (3) Any change to the contents of this page will be notified by NOTAM.