TEL: 82-53-668-0255

FAX: 82-53-668-0277 AFS: RKRRYNYX E-mail: aais@korea.kr

# REPUBLIC OF KOREA

A I P
Supplement 17/21

Ministry of Land, Infrastructure and Transport Office of Civil Aviation

Web: http://ais.casa.go.kr 11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

1 JUL 2021

GEN: NIL

**ENR: NIL** 

A D: SEOUL/Incheon INTL(RKSI)

## **TEMPORARY OBSTACLES ERECTED**

#### 1. INTRODUCTION

Temporary obstacles will be existing on the north side of RWY 16L/34R of Incheon INTL Airport. \*\* The obstacles are located about 1 188 m north from the threshold of RWY 16L/34R.

#### 2. PERIOD

From 1600 UTC 30 JUN 2021 To 0900 UTC 31 OCT 2021

## 3. WORKING AREAS

Position			OBST Type	Height		Radius	Remarks
				AGL	AMSL	Radius	nemarks
1	37°28'59.92"N	126°24'15.98"E	Pump cars Cranes Cargo cranes	20.0 m	24.5 m	30 m	Marked
2	37°29'10.41"N	126°24'34.29"E		20.0 m	24.5 m	30 m	Marked
3	37°28'51.07"N	126°24'23.43"E		20.0 m	24.5 m	30 m	Marked
4	37°29'01.32"N	126°24'42.43"E		20.0 m	24.5 m	30 m	Marked

### 4. REMARKS

- (1) Each crane turns on its axis.
- (2) Works will be conducted by equipments and vehicles in the area as shown in the diagram.
- (3) These cranes do not penetrate the approach, transition and horizontal surface of RKSI.
- (4) Any change to the contents of these pages will be notified by NOTAM.

(AIP SUP 25/20 is hereby superseded)