

TEL : 82-53-668-0255  
FAX : 82-53-668-0277  
AFS : RKRRYNYX  
E-mail : aais@korea.kr  
Web : http://ais.casa.go.kr

# REPUBLIC OF KOREA

Ministry of Land, Infrastructure and Transport  
Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC

AIP

Supplement 12/21

3 JUN 2021

GEN : NIL

ENR : NIL

A D : SEOUL/Gimpo INTL(RKSS)

## OPERATIONAL RESTRICTIONS


### 1. INTRODUCTION

TCLL(Taxiway center line light) for TWY D3 at Gimpo INTL Airport will be phased unserviceable due to replacement.

### 2. PERIOD

From 1400 UTC 2 AUG 2021 To 2100 UTC 11 SEP 2021

### 3. WORKING AREA (See the diagram below)



Location	Period	Working Hours (UTC)
TWY D3	2 AUG 2021 ~ 11 SEP 2021	1400 ~ 2100 Daily

### 4. REMARKS

- (1) During the unserviceable period, low visibility procedure will be changed  
From 2 AUG 2021 To 11 SEP 2021(See the No.5 Low visibility procedure).
- (2) TCLL(Taxiway center line light) for TWY D3 is unserviceable From 2 AUG 2021 To 11 SEP 2021 irrespective of working hours.
- (3) After termination of the daily scheduled flight, work will begin.
- (4) Any change to the contents of these pages will be notified by NOTAM.

5. LOW VISIBILITY PROCEDURE

	Departure	Arrival
14R/L	(See the AIRAC AIP Supplement 7/21 No. 8 Low visibility procedure)	(See the AIRAC AIP Supplement 7/21 No. 8 Low visibility procedure)
32R/L	(See the AIRAC AIP Supplement 7/21 No. 8 Low visibility procedure)	