TEL: 82-53-668-0255 FAX: 82-53-668-0277 AFS: RKRRYNYX

E-mail: aais@korea.kr Web: http://ais.casa.go.kr

REPUBLIC OF KOREA

Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC AIP

Supplement 20/21

21 OCT 2021

GEN: NIL

ENR: NIL

A D: SEOUL/Incheon INTL(RKSI)

RWY 16L/34R AND TWY CLOSED DUE TO CONSTRUCTION

1. INTRODUCTION

- (1) RWY 16L/34R and some parts of TWYs A, N, M will be closed due to pavement construction.
- (2) TWY R10 and some of ACFT stands in apron 2 will be closed due to apron construction.
- (3) Construction work for new TWYs(P3, P9, N7) will be conducted in the closed area A.

2. CLOSED AREAS & PERIOD (See the diagram)

Closed Areas			Period(UTC)
Α		TWY P between TWY P13 and north end of TWY P ** No effect on TWY P13 operation.	From 1600 UTC 1 DEC 2021 To 1600 UTC 26 JAN 2022
	A1	RWY 16L/34R between TWY V and N7 * No effect on TWY V operation.	From 1600 UTC 1 DEC 2021 To 1600 UTC 26 JAN 2022
		TWY N between TWY V and N7 * No effect on TWY V operation.	
	A2	RWY 16L/34R between TWY W and V Metal No effect on TWY W, V operation.	
		Rapid exit TWY N4, N5	
		TWY N between TWY M14 and M17 ** No effect on TWY M14, M17 operation.	
	А3	TWY M between TWY M12 and M14 * No effect on TWY M12, M14 operation.	
	A4	RWY 16L/34R between TWY T and W ** No effect on TWY T, W operation.	
		Rapid exit TWY N2, N3	
		TWY N between TWY M8 and M11 ** No effect on TWY M8, M11 operation.	
	A5	RWY 16L/34R between TWY S and T	
		TWY N1	
В		TWY A between TWY R17 and A19 * No effect on TWY R17 and A19 operation.	From 1600 UTC 1 DEC 2021 To 1600 UTC 26 JAN 2022
С		TWY R10 between TWY R4 and ACFT stand NR. 306 ** No effect on TWY R4 operation.	From 1600 UTC 14 DEC 2021 To 1600 UTC 26 JAN 2022
		ACFT stands NR. 306, 307, 308, 309, 310, 311, 312, 313, 314, 315	

3. REMARKS

- (1) RWY 16L/34R and TWYs will be closed as shown in the diagram.
- (2) Unserviceability lights and frangible barriers will be installed on the closed area.
- (3) All lights including RWY center line lights, RWY edge lights, RWY touchdown lights, Approach lighting system for RWY 34R/16L will be unserviceable.
- (4) Some parts of standard taxi routes(AIP RKSI AD CHART 2-6, 2-7, 2-8, 2-9) and low visibility procedure (AIP RKSI AD 2-29, 2-30, 2-31, 2-32) will be temporarily changed due to the construction.
- (5) Standard taxi routes of the closed area will be changed by the ATC instruction.
- (6) TWY center line lights, TWY edge lights, Stop bar lights and TWY guidance sign for the closed area will not be operated.
- (7) Works by equipment and vehicles will be conducted in the working area as shown in the diagram.
- (8) Any change to the contents of these pages will be notified by NOTAM.











