TEL: 82-32-880-0256 FAX: 82-32-889-5902 AFS: RKRRYNYX

E-mail: aisd@korea.kr Web: http://ais.casa.go.kr

# REPUBLIC OF KOREA

# Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC AIP

**Supplement 4/22 10 MAR 2022** 

GEN: NIL

**ENR: NIL** 

A D: SEOUL/Incheon INTL(RKSI)

### ACFT STANDS CLOSED DUE TO REMOTE BOARDING FACILITY CONSTRUCTION

#### 1. INTRODUCTION

ACFT stands NR. 341, 342, 343, 344 will be closed due to remote boarding facility construction.

### 2. PERIOD

From 1600 UTC 20 APR 2022 To 1600 UTC 19 APR 2023

#### 3. WORKING & CLOSED AREAS (See the diagram)

No.	Position		Closed Areas
1	37°28'23.59"N	126°26'19.32"E	
2	37°28'23.58"N	126°26'19.50"E	
3	37°28'21.68"N	126°26'21.20"E	
4	37°28'21.12"N	126°26'21.70"E	
5	37°28'17.31"N	126°26'25.09"E	ACFT stands NR. 341, 342, 343, 344
6	37°28'17.17"N	126°26'25.06"E	※ No effect on ACFT stand NR. 345 operation.
7	37°28'16.04"N	126°26'23.18"E	·
8	37°28'19.33"N	126°26'20.25"E	
9	37°28'22.45"N	126°26'17.48"E	
10	37°28'22.59"N	126°26'17.52"E	

## 4. REMARKS

- (1) Safety fence will be installed to indicate the working area.
- (2) This work has no effect on RWY 15R/33L and TWY R1 normal operations.
- (3) Works will be conducted by equipments and vehicles in the area as shown in the diagram.
- (4) Equipments and vehicles do not penetrate obstacle limitation surfaces.
- (5) During working period, pilots should exercise caution and follow ATC's instruction when taxiing ACFT near the working area.
- (6) Any change to the contents of these pages will be notified by NOTAM.

# 5. DIAGRAM A15 M15 346 Working Area 343 $\mathbf{Q}$ M14 A14 Passenger Terminal 2 M13 247 248 249 250 251 252 253 A13 В 259 260 237 239 241 238 240 Closed Area