

TEL : 82-32-880-0256
FAX : 82-32-889-5902
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 13/22
5 MAY 2022

GEN : NIL

ENR : NIL

A D : SEOUL/Gimpo INTL(RKSS)

OPERATIONAL RESTRICTIONS

1. INTRODUCTION

- (1) TDZL(Touch-down zone light) for RWY 14R at Gimpo INTL Airport will be phased unserviceable due to replacement.
- (2) TCLL(Taxiway center line light), IHPL(Intermediate holding position light) for TWY P at Gimpo INTL Airport will be phased unserviceable due to replacement.

2. PERIOD

From 1400 UTC 16 JUN 2022 To 2100 UTC 30 SEP 2022

3. WORKING AREAS (See the diagram below)

No.	Location	Period	Working Hours (UTC)
①	RWY 14R	1 JUL 2022 ~ 30 SEP 2022	1400 ~ 2100 Daily
②	TWY P	16 JUN 2022 ~ 16 AUG 2022	

4. REMARKS

- (1) TDZL(Touch-down zone light) for RWY 14R(area ①) is unserviceable From 1 JUL 2022 To 30 SEP 2022 irrespective of working hours.
- (2) TCLL(Taxiway center line light), IHPL(Intermediate holding position light) for TWY P is unserviceable From 16 JUN 2022 To 16 AUG 2022 irrespective of working hours.
- (3) During the period(From 1 JUL 2022 To 30 SEP 2022), RWY 14R CAT-II, III operation is not available.
- (4) If low visibility procedures operated in case of less than 400 m, follow me car service will be provided for aircraft using area ②.
- (5) After termination of the daily scheduled flight, work will begin.
- (6) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

<Lighting aids RWY 14R/32L and 14L/32R and exit TWY>

