

TEL : 82-32-880-0256
FAX : 82-32-889-5902
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : <http://ais.casa.go.kr>

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

A I P
Supplement 21/22
2 JUN 2022

GEN : NIL

ENR : NIL

A D : SEOUL/Gimpo INTL(RKSS)

OPERATIONAL RESTRICTIONS

1. INTRODUCTION

- (1) Some part of taxiway P at Gimpo INTL Airport will be unusable for code "F" ACFT due to pavement and drainage repairs.
- (2) Code "F" ACFT taxiing route will be changed during the period.

2. PERIOD

From 1600 UTC 13 JUL 2022 To 1600 UTC 29 DEC 2022


3. WORKING AREA

Refer to the next page (See the diagram 5)


4. REMARKS

- (1) During the period, code "F" aircraft taxi procedures will be changed.
(Refer to the diagram NR. 6 low visibility procedures and NR. 7 "F" aircraft available taxi route.)
- (2) Safety fences and lights will be installed to indicate the working area.
- (3) When low visibility procedures are operated, follow me car service will be available to ACFT taxiing down RWY 32R/14L.
- (4) Any change to the contents of these pages will be notified by NOTAM.


5. DIAGRAM



6. LOW VISIBILITY PROCEDURE (Available for code letter "F" aircraft)



Standard & SMGCS taxi route



14R

7. "F" ACFT AVAILABLE TAXI ROUTE

