

TEL : 82-32-880-0256
FAX : 82-32-889-5902
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 16/22
28 JUL 2022

GEN : NIL

ENR : NIL

A D : MUAN/Muan INTL(RKJB)

UNSERVICEABILITY OF ILS/DME

1. INTRODUCTION

The ILS/DME for RWY 01 at Muan INTL Airport will be unserviceable due to RWY 01 GP/DME replacement.

2. PERIOD

From 1600 UTC 7 SEP 2022 To 1600 UTC 28 DEC 2022

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates
GP 01	-	331.1 MHz	34°58'53.3"N 126°22'54.0"E
DME 01	IMUN	(TX)1017.0 MHz (RX)1080.0 MHz (CH 56X)	34°58'53.2"N 126°22'53.8"E
LOC 01		111.9 MHz	35°00'23.1"N 126°22'57.8"E

4. WORKING AREA

Informations related to working area will be notified by NOTAM(Only when WIP).

5. REMARKS

(1) During the replacement period, some flight procedures of RKJB will not be available as follows.

	RWY	Procedure	AIP Page
Instrument Approach	01	ILS Y or LOC Y RWY 01	RKJB AD CHART 2-14
	01	ILS Z or LOC Z RWY 01	RKJB AD CHART 2-15

(2) Any change to the contents of this page will be notified by NOTAM.