

TEL : 82-32-880-0256
FAX : 82-32-889-5902
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 36/22
15 DEC 2022

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

**ACFT STANDS CLOSED DUE TO REMOTE BOARDING
FACILITY CONSTRUCTION**

1. INTRODUCTION

ACFT stands NR. 501, 502, 503, 504 will be closed due to remote boarding facility construction.

2. PERIOD

From 1600 UTC 14 DEC 2022 To 1600 UTC 19 APR 2023

3. WORKING & CLOSED AREAS (※ See the diagram)

NR.	Position		Closed Areas
①	37°28'23.59"N	126°26'19.32"E	ACFT stands NR. 501, 502, 503, 504 ※ No effect on ACFT stand NR. 505 operation.
②	37°28'23.58"N	126°26'19.50"E	
③	37°28'21.68"N	126°26'21.20"E	
④	37°28'21.12"N	126°26'21.70"E	
⑤	37°28'17.31"N	126°26'25.09"E	
⑥	37°28'17.17"N	126°26'25.06"E	
⑦	37°28'16.04"N	126°26'23.18"E	
⑧	37°28'19.33"N	126°26'20.25"E	
⑨	37°28'22.45"N	126°26'17.48"E	
⑩	37°28'22.59"N	126°26'17.52"E	

4. REMARKS

- (1) Safety fence will be installed to indicate the working area.
- (2) This work has no effect on RWY 15R/33L and TWY R1 normal operations.
- (3) Works will be conducted by equipments and vehicles in the area as shown in the diagram.
- (4) Equipments and vehicles do not penetrate obstacle limitation surfaces.
- (5) During working period, pilots should exercise caution and follow ATC's instruction when taxiing ACFT near the working area.
- (6) Any change to the contents of these pages will be notified by NOTAM.

(AIRAC AIP SUP 4/22 is hereby superseded)

5. DIAGRAM

