

TEL : 82-32-880-0256
FAX : 82-32-889-5902
AFS : RKRYYNYX
E-mail : aisd@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 12/23
9 MAR 2023

GEN : NIL

ENR : NIL

A D : MUAN/Muan INTL(RKJB)

UNSERVICEABILITY OF ILS/DME

(Effective : 1600 UTC 19 APR 2023)

1. INTRODUCTION

The ILS/DME for RWY 19 at RKJB will be U/S due to RWY 19 LOC replacement WIP.

2. PERIOD

From 1600 UTC 19 APR 2023 To 1600 UTC 12 JUL 2023

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates
GP 19	-	329.3 MHz	35°00'04.3"N 126°22'53.5"E
DME 19	IMAN	(TX)987 MHz (RX)1050 MHz (CH 26X)	34°00'04.3"N 126°22'53.3"E
LOC 19		108.9 MHz	34°58'35.0"N 126°22'58.5"E

4. WORKING AREA

NR.	Position	Remarks
①	34°58'35.4"N 126°22'57.65"E	Marked and Lighted
②	34°58'35.4"N 126°23'01.4"E	
③	34°58'33.8"N 126°23'01.4"E	
④	34°58'33.8"N 126°22'57.65"E	

5. REMARKS

(1) During the replacement period, some flight procedures of RKJB will not be available as follows.

	RWY	Procedure	AIP Page
Instrument Approach	19	ILS Y or LOC Y RWY 19	RKJB AD CHART 2-18
	19	ILS Z or LOC Z RWY 19	RKJB AD CHART 2-19

(2) Any change to the contents of these pages will be notified by NOTAM.

NOT TO SCALE

