TEL: 82-53-668-0284

FAX: 82-53-668-0277 AFS: RKRRYNYX E-mail: aisd@korea.kr

# REPUBLIC OF KOREA

AIP

Ministry of Land, Infrastructure and Transport Office of Civil Aviation Supplement 14/23

27 JUL 2023

Web: https://aim.koca.go.kr 11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

GEN: NIL

**ENR: NIL** 

A D: ULSAN/Ulsan(RKPU)

## UNSERVICEABILITY OF ULSAN RADAR

## 1. INTRODUCTION

The primary and secondary surveillance radar at Ulsan Airport will be unserviceable due to replacement work.

## 2. PERIOD

From 1500 UTC 2 JUL 2023 To 1459 UTC 3 DEC 2023

## 3. FLIGHT PROCEDURE RESTRICTION

(1) Some flight procedures of RKPU will not be available as follows.

	RWY	Procedure	AIP Page
SID	18	RNAV KPO 1M, RNAV APARU 1M	RKPU AD CHART 2-6
	36	RNAV KPO 1R, RNAV APARU 1R	RKPU AD CHART 2-8
Instrument Approach	36	ILS Z or LOC Z	RKPU AD CHART 2-16

<sup>(2)</sup> STAR procedures of RKPU are available by using Pohang radar.

## 4. REMARK

Any change to the contents of this page will be notified by another AIP SUP or NOTAM.