TEL: 82-53-668-0286

FAX: 82-53-668-0277 AFS: RKRRYNYX E-mail: aisd@korea.kr

REPUBLIC OF KOREA

AIP

Ministry of Land, Infrastructure and Transport
Office of Civil Aviation

Supplement 19/23

16 NOV 2023

Web: https://aim.koca.go.kr 11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

GEN: NIL

ENR: NIL

A D: ULSAN/Ulsan(RKPU)

UNSERVICEABILITY OF ULSAN RADAR

1. INTRODUCTION

The primary and secondary surveillance radar at Ulsan Airport will be unserviceable due to replacement work.

2. PERIOD

From 1500 UTC 2 JUL 2023 To 1459 UTC 30 JUN 2024

3. FLIGHT PROCEDURE RESTRICTION

(1) Some flight procedures of RKPU will not be available as follows.

	RWY	Procedure	AIP Page
SID	18	RNAV KPO 1M, RNAV APARU 1M	RKPU AD CHART 2-6
	36	RNAV KPO 1R, RNAV APARU 1R	RKPU AD CHART 2-8
Instrument Approach	36	ILS Z or LOC Z	RKPU AD CHART 2-16

⁽²⁾ STAR procedures of RKPU are available by using Pohang radar.

4. REMARK

Any change to the contents of this page will be notified by another AIP SUP or NOTAM.

(AIP SUP 14/23 is hereby superseded)