

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : <https://aim.koca.go.kr>

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 49/24
19 SEP 2024

GEN : NIL

ENR : NIL

A D : ULSAN/Ulsan(RKPU)

UNSERVICEABILITY OF ULSAN RADAR

1. INTRODUCTION

The primary and secondary surveillance radar at Ulsan Airport will be unserviceable due to replacement work.

2. PERIOD

From 1500 UTC 2 JUL 2023 To 1459 UTC 29 NOV 2024

3. FLIGHT PROCEDURE RESTRICTION

(1) Some flight procedures of RKPU will not be available as follows.

Chart	RWY	Procedure ID	AIP Page
SID	18	RNAV KPO 1M, RNAV APARU 1M	RKPU AD CHART 2-6
	36	RNAV KPO 1R, RNAV APARU 1R	RKPU AD CHART 2-8
Instrument Approach	36	ILS Z or LOC Z	RKPU AD CHART 2-16

(2) STAR procedures of RKPU are available by using Pohang radar.

4. REMARK

Any change to the contents of this page will be notified by another AIP SUP or NOTAM.

(AIP SUP 31/24 is hereby superseded)