

TEL : 82-53-668-0284
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : https://aim.koca.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 16/23
1 JUN 2023

GEN : NIL

ENR : NIL

A D : POHANG/Pohang Gyeongju(RKTH)

UNSERVICEABILITY OF LOC/DME

1. INTRODUCTION

The LOC/DME for RWY 10 at Pohang Gyeongju Airport will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 12 JUL 2023 To 1600 UTC 29 NOV 2023

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates	AIP Page
LOC 10	IKPO	110.9 MHz	35°59'17.1"N 129°26'02.4"E	RKTH AD 2-8
DME 10		1007 MHz (CH 46X)	35°59'15.7"N 129°26'04.2"E	RKTH AD 2-8

4. WORKING AREA

See the below diagram.


5. REMARKS

(1) During the replacement period, some flight procedures of RKTH will not be available as follow.

	RWY	Procedure	AIP Page
Instrument Approach	10	LOC/DME RWY 10	RKTH AD CHART 2-11

(2) Any change to the contents of these pages will be notified by another AIP SUP or NOTAM.

6. DIAGRAM



NOT TO SCALE