

TEL : 82-53-668-0284
FAX : 82-53-668-0277
AFS : RKRYYNYX
E-mail : aisd@korea.kr
Web : https://aim.koca.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 22/23
27 JUL 2023

GEN : NIL

ENR : NIL

A D : ULJIN/Uljin(RKTL)

UNSERVICEABILITY OF UJN VORTAC

1. INTRODUCTION

The VORTAC(UJN) at Uljin Aerodrome will be unserviceable due to VOR/DME replacement.

2. PERIOD

From 1500 UTC 26 JUL 2023 To 1600 UTC 6 SEP 2023

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates	AIP Page
VORTAC	UJN	115.3 MHz (CH 100X)	36°46'35.2"N 129°27'26.9"E (VORTAC)	RKTL AD 2-7

4. REMARKS

(1) During the replacement period, some flight procedures of RKTL **will not be available** as follows.

RKTL	RWY	Procedure	AIP Page
SID	17	NOBUT 2S / LOSTO 2S	RKTL AD CHART 2-8
		LOSTO 6S	RKTL AD CHART 2-9
	35	NOBUT 2N / LOSTO 2N	RKTL AD CHART 2-11
		LOSTO 1A	RKTL AD CHART 2-12
		RADAR 1A	RKTL AD CHART 2-13
STAR	17	NOBUT 2D / LOSTO 2D	RKTL AD CHART 2-15
	35	NOBUT 2C / LOSTO 2C	RKTL AD CHART 2-17
Instrument Approach	17	ILS Y or LOC Y RWY 17	RKTL AD CHART 2-19
		VOR RWY 17	RKTL AD CHART 2-21
	35	ILS Y or LOC Y RWY 35	RKTL AD CHART 2-23
		VOR RWY 35	RKTL AD CHART 2-25

(2) During the replacement period, flight procedures of RKTL **will be available** radar vector.

(3) Any change to the contents of these pages will be notified by NOTAM.

(AIRAC AIP SUP 1/23 is hereby superseded)

5. DIAGRAM

