

TEL : 82-53-668-0284
FAX : 82-53-668-0277
AFS : RKRYYNYX
E-mail : aisd@korea.kr
Web : https://aim.koca.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 20/23
27 JUL 2023

GEN : NIL

ENR : NIL

A D : MUAN/Muan INTL(RKJB)

UNSERVICEABILITY OF ILS/DME

1. INTRODUCTION

The ILS/DME for RWY 19 at RKJB will be U/S due to RWY 19 LOC replacement WIP.

2. PERIOD

From 1600 UTC 6 SEP 2023 To 1600 UTC 27 DEC 2023

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates
GP 19	-	329.3 MHz	35°00'04.3"N 126°22'53.5"E
DME 19	IMAN	(TX)987 MHz (RX)1050 MHz (CH 26X)	34°00'04.3"N 126°22'53.3"E
LOC 19		108.9 MHz	34°58'35.0"N 126°22'58.5"E

4. WORKING AREA

NR.	Position	Remarks
①	34°58'35.4"N 126°22'57.65"E	Marked and Lighted
②	34°58'35.4"N 126°23'01.4"E	
③	34°58'33.8"N 126°23'01.4"E	
④	34°58'33.8"N 126°22'57.65"E	

5. REMARKS


(1) During the replacement period, some flight procedures of RKJB will not be available as follows.

	RWY	Procedure	AIP Page
Instrument Approach	19	ILS Y or LOC Y RWY 19	RKJB AD CHART 2-18
	19	ILS Z or LOC Z RWY 19	RKJB AD CHART 2-19

(2) There is a possibility that moving vehicles may pass by the construction area.

(3) Any change to the contents of these pages will be notified by NOTAM.

6. DIAGRAM



NOT TO SCALE