

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : <https://aim.koca.go.kr>

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 26/23
19 OCT 2023

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

UNSERVICEABILITY OF PAPI/ALS FOR RWY 16L/34R

1. INTRODUCTION

The PAPI/ALS for RWY 16L/34R at Incheon INTL Airport will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 29 NOV 2023 To 1600 UTC 31 JUL 2024

3. WORKING AREAS

See the diagram.

4. REMARKS

- (1) RWY 16L/34R will be available only for departure.
- (2) Precision approach path indicator and Approach lighting systems for RWY 16L/34R will be unserviceable.
- (3) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

