

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKKRYNYX
E-mail : aisd@korea.kr
Web : <https://aim.koca.go.kr>

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 34/24
27 JUN 2024

GEN : NIL

ENR : NIL

A D : JEJU/Jeju INTL(RKPC)

UNSERVICEABILITY OF ILS/DME FOR RWY 07

1. INTRODUCTION

The ILS/DME for RWY 07 at Jeju INTL Airport will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 7 AUG 2024 To 1600 UTC 16 APR 2025

3. RADIO NAVIGATION AND LANDING AIDS INFO

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates	AIP Page
LOC 07	ICJU	109.9 MHz	33°30'58.7"N 126°30'01.6"E	RKPC AD 2-8
DME 07		997 MHz (CH 36X)	33°30'09.0"N 126°28'15.7"E	
GP 07	-	333.8 MHz	33°30'08.9"N 126°28'15.7"E	
IM 07	-	75 MHz	33°29'54.3"N 126°27'56.2"E	

4. WORKING AREA

See the BLW diagram.

5. REMARKS

(1) During the replacement period, some flight procedures of RKPC will not be available as follows.

	RWY	Procedure	AIP Page
Instrument Approach	07	ILS Z or LOC Z RWY 07 CAT I & II	RKPC AD CHART 2-22
		ILS Y or LOC Y RWY 07 CAT I & II	RKPC AD CHART 2-23

(2) Take-off weather minima with certified TGS(Take-off guidance system) for RWY 07 of RKPC will not be available.

(3) Take-off from RWY 07 of RKPC will not be available in a visibility of less than RVR 150 m.

(4) OBSTs don't penetrate any obstacle limitation surfaces of RKPC.

(5) Any change to the contents of these pages will be notified by another NOTAM.

6. DIAGRAM

