

TEL : 82-53-668-0286  
FAX : 82-53-668-0277  
AFS : RKRRYNYX  
E-mail : aisd@korea.kr  
Web : https://aim.koca.go.kr

**REPUBLIC OF KOREA**  
**Ministry of Land, Infrastructure and Transport**  
**Office of Civil Aviation**  
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

**AIRAC**  
**AIP**  
**Supplement 38/24**  
**25 JUL 2024**

**GEN : NIL**

**ENR : NIL**

**A D : SEOUL/Incheon INTL(RKSI)**

**RWY 15L/33R AND TWYs CLOSED DUE TO CONSTRUCTION**

**1. INTRODUCTION**

- (1) RWY 15L/33R will be closed due to pavement construction.
- (2) Some parts of TWY D will be closed due to pavement construction.

**2. CLOSED AREAS & PERIOD** (See the diagram)


| Closed Areas |                                                                              | Period(UTC)                                         |
|--------------|------------------------------------------------------------------------------|-----------------------------------------------------|
| A            | RWY 15L/33R between TWY K and J<br>※ No effect on TWY K and J operation.     | From 0300 UTC 8 AUG 2024<br>To 0300 UTC 13 DEC 2024 |
|              | TWY D between TWY D3 and TWY D4                                              |                                                     |
|              | Rapid exit TWY C1, C2, C4, C5                                                |                                                     |
|              | Rapid exit TWY D1, D6                                                        |                                                     |
| B            | RWY 15L/33R between TWY K and TWY L<br>※ No effect on TWY K and L operation. | From 0300 UTC 8 AUG 2024<br>To 0300 UTC 13 DEC 2024 |

**3. REMARKS**

- (1) RWY 15L/33R and TWYs will be closed as shown in the diagrams.
- (2) Unserviceable lights and frangible barriers will be installed on the closed area.
- (3) All lights including RWY centerline lights, RWY edge lights, RWY touchdown lights, Approach lighting system for RWY 15L/33R will be unserviceable.
- (4) Some parts of standard taxi routes(AIP RKSI AD CHART 2-6, 2-7, 2-8, 2-9) and low visibility procedure (AIP RKSI AD 2-29, 2-30, 2-31, 2-32) will be temporarily changed due to the construction.
- (5) Temporary taxi routes may be changed by the ATC instruction.
- (6) TWY centerline lights, TWY edge lights, Stop bar lights and Taxiway guidance sign for the closed area will not be operated.
- (7) Works by equipment and vehicles will be conducted in the working area as shown in the diagrams.
- (8) Closed runway lighting is operated from 0800 to 2300 UTC at the thresholds of RWY 33R.
- (9) Refer to AIRAC AIP SUP[18/23] "UNSERVICEABILITY OF ILS/DMEs" for aircraft movement on RWY 16L/34R.
- (10) Any change to the contents of these pages will be notified by NOTAM.


*(AIRAC AIP SUP 32/24 is hereby superseded)*

#### 4. DIAGRAMS




# Temporary Taxi Routes (AIP RKSİ AD CHART 2-7, 2-9 and AD 2-29)

Arrival for RWY 15L/R, 16L/R




# **Temporary Taxi Routes** (AIP RKSI AD CHART 2-6, 2-8 and AD 2-32)

Departure for 15L/R, 16L/R



# **Temporary Taxi Routes** (AIP RKSI AD CHART 2-7, 2-9 and AD 2-30)

Arrival for RWY 33L/R, 34L/R



# **Temporary Taxi Routes** (AIP RKSI AD CHART 2-6, 2-8 and AD 2-31)

Departure for RWY 33L/R, 34L/R

