

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : https://aim.koca.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 56/24
19 SEP 2024

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

UNSERVICEABILITY OF WNG VOR/DME

(Effective : 1600UTC 30 OCT 2024)

1. INTRODUCTION

The WNG VOR/DME at Incheon INTL Airport will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 30 OCT 2024 To 1600 UTC 30 JUN 2025

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid, MAG VAR, Type of Supported OPS	ID	Frequency	Hours of Operation	Position of Transmitting Antenna Coordinates	AIP Page
VOR/DME	WNG	112.90 MHz (CH 76X)	H24	37°25'58.6"N 126°27'00.0"E	RKSI AD 2-14

4. REMARKS

(1) During the replacement period, some flight procedures of RKSI will be available restrictively as follows.

RKSI	RWY	Procedure	AIP page	Alternative Procedure
SID	15L/R	RADAR 5S	RKSI AD CHART 2-33	Use NCN or SEL or SOT.
	16L/R	RADAR 3U	RKSI AD CHART 2-33	Use NCN or SEL or SOT.
	33L/R	RADAR 3A	RKSI AD CHART 2-40	Use NCN or SEL or SOT.
	34L/R	RADAR 3D	RKSI AD CHART 2-40	Use NCN or SEL or SOT.
INSTR APCH	16L	ILS or LOC	RKSI AD CHART 2-58 (MISSED APCH)	Refer to RKSI AD 2.22-1.9.
	16R	ILS or LOC	RKSI AD CHART 2-60 (MISSED APCH)	
	34L	ILS or LOC	RKSI AD CHART 2-67 (MISSED APCH)	Refer to RKSI AD 2.22-1.9.
	34R	ILS or LOC	RKSI AD CHART 2-69 (MISSED APCH)	

a. ACFT shall advise ATC(Seoul APP / Incheon TWR) for alternatives.

b. RADAR service will be provided by Seoul APP.

(2) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

