

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : https://aim.koca.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 43/25
1 MAY 2025

GEN : NIL

ENR : SONGTAN VORTAC(SOT)

A D : SEOUL/Incheon INTL(RKSI) / SEOUL/Gimpo INTL(RKSS)

UNSERVICEABILITY OF SONGTAN VORTAC

(Effective : 1600UTC 11 JUN 2025)

1. INTRODUCTION

The SONGTAN VORTAC(SOT) will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 11 JUN 2025 To 1600 UTC 8 JUL 2026

3. RADIO NAVIGATION AID INFO

Name of Station (VAR) (VOR: Declination)	ID	Frequency (CH)	Coordinates	ELEV DME Antenna (ft AMSL)
SONGTAN VORTAC (8° W)	SOT	116.9 MHz (CH 116X)	37°05'40"N 127°01'54"E	100

4. REMARKS

(1) En-route / Flight Planning

- Use 37°05'40"N 127°01'54"E instead of SOT.
- Can not use DME/DME navigation on airway using SOT as critical DME.
- Non-RNAV ACFT request radar vector to Dague / Incheon ACC before flying on the airways within the SOT coverage.

(2) Flight Procedure

- During the replacement period, some flight procedures of RKSI will not be available as follows.

RKSI	RWY	Procedures	AIP Page
SID	15L	SOT 1S	RKSI AD CHART 2-30
	15R		
	33L	SOT 1A	RKSI AD CHART 2-37
	33R		
STAR	15L	GUKDO 1A	RKSI AD CHART 2-42
	15L	KARBU 1A	

- During the replacement period, some flight procedures of RKSS will not be available as follows.

RKSS	RWY	Procedures	AIP Page
SID	14L	SOT 1E	RKSS AD CHART 2-17
	14R		
	32L	SOT 1W	RKSS AD CHART 2-20
	32R		

- ACFT shall advise ATC (Seoul APP / Incheon TWR / Seoul DEP / Gimpo TWR) for alternatives.
- Radar service will be provided by Seoul APP.

- Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

