

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : <https://aim.koca.go.kr>

REPUBLIC OF KOREA

Ministry of Land, Infrastructure and Transport
Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC

AIP

Supplement 46/25

1 MAY 2025

GEN : NIL

ENR : NIL

A D : JEJU/Jeju INTL(RKPC)

OPERATIONAL RESTRICTIONS

(Effective : 1600UTC 11 JUN 2025)

1. INTRODUCTION

The TCLL for TWY P5 at Jeju INTL Airport will be unserviceable due to replacement.

2. PERIOD

From 1400 UTC 12 JUN 2025 To 2100 UTC 9 JUL 2025

3. WORKING AREA (See the diagram below)

Area	Location	Period	Working Hours (UTC)
TWY	TWY P5	From 12 JUN 2025 To 9 JUL 2025	1400 ~ 2100 Daily

4. REMARKS

- (1) TCLL(Taxiway center line light) for TWY P5 is unserviceable From 12 JUN 2025 To 9 JUL 2025 irrespective of working hours.
- (2) After termination of the daily scheduled flight, work will begin.
- (3) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

