

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : <https://aim.koca.go.kr>

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 58/25
26 JUN 2025

GEN : NIL

ENR : NIL

A D : JEJU/Jeju INTL(RKPC)

UNSERVICEABILITY OF ILS/DME FOR RWY 25

(Effective : 1600UTC 6 AUG 2025)

1. INTRODUCTION

The ILS/DME for RWY 25 at Jeju INTL Airport will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 6 AUG 2025 To 1600 UTC 15 APR 2026

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates	AIP page
LOC 25	ICHE	111.3 MHz	33°29'54.4"N 126°27'56.4"E	RKPC AD 2-8
DME 25	-	1011 MHz (CH 50X)	33°30'51.4"N 126°29'39.1"E	
GP 25	-	332.3 MHz	33°30'51.2"N 126°29'39.2"E	

4. WORKING AREA

See the diagram below.

5. REMARKS

(1) During the replacement period, some flight procedures of Jeju INTL Airport will not be available as follows.

	RWY	Procedures	AIP Page
Instrument Approach	25	ILS Z or LOC Z RWY 25	RKPC AD CHART 2-26
		ILS Y or LOC Y RWY 25	RKPC AD CHART 2-27

(2) Take-off weather minima with certified TGS(Take-off guidance system) for RWY 25 of Jeju INTL Airport will not be available.

(3) Take-off from RWY 25 of Jeju INTL Airport will not be available in a visibility of less than RVR 150 m.

(4) Obstacles for construction don't penetrate any obstacle limitation surfaces of RKPC.

(5) Any change to the contents of these pages will be notified by NOTAM.

6. DIAGRAM

