TEL: 82-53-668-0286 FAX: 82-53-668-0277

AFS: RKRRYNYX E-mail: aisd@korea.kr

Web: https://aim.koca.go.kr

REPUBLIC OF KOREA

Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP

Supplement 88/25

16 OCT 2025

GEN: NIL

ENR: NIL

A D: SEOUL/Incheon INTL(RKSI)

TEMPORARY OBSTACLES ERECTED

1. INTRODUCTION

The obstacles will be installed to the south between RWY 15R/33L and RWY 16L/34R of Incheon INTL Airport. ** The obstacles are located about 1 700 m to the southwest from the southern end of RWY 15R/33L.

2. PERIOD

From 1500 UTC 16 OCT 2025 To 1500 UTC 31 OCT 2026

3. WORKING AREAS (* See the diagram)

NR.	Position		OBST Type	Height		Remarks
INIT.				AGL	AMSL	nemarks
1	37°26'17.0000"N	126°27'45.0000"E		48.80 m	53.80 m	
2	37°26'15.0000"N	126°27'47.0000"E		48.80 m	53.80 m	
3	37°26'13.0000"N	126°27'48.0000"E		48.80 m	53.80 m	
4	37°26'11.0000"N	126°27'44.0000"E		48.80 m	53.80 m	
5	37°26'10.0000"N	126°27'41.0000"E	Crane	48.80 m	53.80 m	Marked
6	37°26'13.0000"N	126°27'40.0000"E		48.80 m	53.80 m	
7	37°26'15.0000"N	126°27'40.0000"E		48.80 m	53.80 m	
8	37°26'16.0000"N	126°27'43.0000"E		48.80 m	53.80 m	
9	37°26'17.0000"N	126°27'45.0000"E		48.80 m	53.80 m	

4. REMARKS

- (1) Each crane turns on its axis(Radius 30 m).
- (2) Works will be conducted by equipments and vehicles in the area as shown in the diagrams.
- (3) These cranes penetrate the horizontal surface of RKSI.
- (4) Marking flags will be installed on the top of the every crane.
- (5) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM



