TEL: 82-53-668-0286 FAX: 82-53-668-0277

AFS: RKRRYNYX
E-mail: aisd@korea.kr
Web: https://aim.koca.go.kr

## REPUBLIC OF KOREA

Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC AIP

Supplement 94/25

16 OCT 2025

GEN: NIL

**ENR: NIL** 

A D: YANGYANG/Yangyang INTL(RKNY)

# TEMPORARY CHANGES OF STANDARD DEPARTURE CHART INSTRUMENT(SID) FOR YANGYANG INTL AIRPORT

(Effective: 1600UTC 26 NOV 2025)

#### 1. INTRODUCTION

The following SIDs for Yangyang INTL Airport are changed temporarily due to newly identified tower crane activity near Yangyang INTL Airport.(Changes are indicated by highlighted text.) \*\* This AIRAC AIP SUP is associated with NOTAM NR. A1163/25 and A1164/25.

#### 2. PERIOD


From 1600 UTC 26 NOV 2025 To 1500 UTC 28 FEB 2026

### 3. TEMPORARY CHANGES OF DEPARTURE PROCEDURES

RWY	Title of Procedure	Changes	AIP Page
	RNAV KAE 2N RNAV BIKSI 2N RNAV PILIT 2N	GENERAL INFORMATION	RKNY AD CHART 2-10
		2. 6.6% climb is required for ATC purpose and 4.3% climb is required until reaching 1 100 ft for OBST avoidance.	
33	YAG 2A	GENERAL INFORMATION	RKNY AD CHART 2-11
		1. CG in excess of 3.3% necessary for OBST avoidance, Airspace and ATC purpose.  - Minimum 7.8%(for CAT A&B) and 8.0% (for CAT C&D) CG are required until reaching 9 000 ft for Airspace and ATC purpose.  - Minimum 4.3% climb is required until reaching 1 100 ft for OBST avoidance.	

#### 4. REMARKS

- (1) Refer to NOTAM NR. A1151/25 and AIRAC AIP SUP 87/25 for instrument approach procedure operations. For further details, contact +82-33-670-7201.
- (2) Any change to the contents of these pages will be notified by NOTAM.



Change: Information of standard instrument departure procedure for RWY 33.

OFFICE OF CIVIL AVIATION

