

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : https://aim.koca.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 108/25
13 NOV 2025

GEN : NIL

ENR : NIL

A D : GWANGJU/Gwangju INTL(RKJJ)

UNSERVICEABILITY OF ILS/DME FOR RWY 04R

(Effective : 1600UTC 24 DEC 2025)

1. INTRODUCTION

The ILS/DME for RWY 04R at Gwangju Airport will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 24 DEC 2025 To 1600 UTC 16 APR 2026

3. RADIO NAVIGATION AND LANDING AIDS INFORMATION

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates	AIP page
GP 04R	-	331.7 MHz	35°06'59.3"N 126°48'17.3"E	RKJJ AD 2-9 (13 JAN 2022)
DME 04R	IMDG	(TX)1009.0 MHz (RX)946.0 MHz (CH 48X)	35°06'59.3"N 126°48'17.4"E	
LOC 04R		111.1 MHz	35°08'21.5"N 126°49'09.4"E	

4. WORKING AREA

See the BLW diagram.

5. REMARKS

(1) During the replacement period, some flight procedures of RKJJ will not be available as follows.

	RWY	Procedure	AIP Page
Instrument Approach	04R	ILS/DME RWY 04R	RKJJ AD CHART 2-20 (11 JAN 2024)
		LOC/DME RWY 04R	RKJJ AD CHART 2-21 (11 JAN 2024)

(2) Any change to the contents of these pages will be notified by NOTAM.

(AIRAC AIP SUP 45/24 is hereby superseded)

[illegible]