

TEL : 82-53-668-0255
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aais@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 20/21
1 JUL 2021

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

TEMPORARY OBSTACLES ERECTED

1. INTRODUCTION

The obstacles will be installed at the east side of RWY 15L/33R of Incheon INTL Airport.

※ The obstacles are located about 4 360 m to the east from the centerline of RWY 15L/33R.

2. PERIOD

From 1600 UTC 30 JUN 2021 To 0900 UTC 31 JAN 2022

3. WORKING AREAS


Position			OBST Type	Height		Remarks
				AGL	AMSL	
①	37°28'50.76412"N	126°30'08.44197"E	Tower Crane	84.94 m	94.24 m	Marked and Lighted
②	37°28'49.67851"N	126°30'11.09081"E		92.45 m	101.75 m	
③	37°28'48.22183"N	126°30'13.21616"E		84.94 m	94.24 m	
④	37°28'46.95256"N	126°30'15.63288"E		79.98 m	89.28 m	
⑤	37°28'50.08302"N	126°30'17.45719"E		92.45 m	101.75 m	
⑥	37°28'51.34773"N	126°30'14.78953"E		83.45 m	92.75 m	
⑦	37°28'53.19935"N	126°30'14.78953"E		84.94 m	94.24 m	
⑧	37°28'52.21543"N	126°30'09.83623"E		83.45 m	92.75 m	

4. REMARKS

- (1) Each tower crane turns on its axis(Radius 40 ~ 60 m).
- (2) These tower cranes penetrate the conical surface of RKSI.
- (3) Lights will be installed on the top of the every tower crane.
- (4) Any change to the contents of these pages will be notified by NOTAM.

(AIP SUP 5/21 is hereby superseded)

5. DIAGRAM



NOT TO SCALE