

TEL : 82-53-668-0255
FAX : 82-53-668-0277
AFS : RKRYYNYX
E-mail : aais@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 13/21
3 JUN 2021

GEN : NIL

ENR : JEJU VORTAC(CJU)

A D : JEJU/Jeju INTL(RKPC)

UNSERVICEABILITY OF JEJU VORTAC

1. INTRODUCTION

The JEJU VORTAC(CJU) will be unserviceable due to replacement.

2. PERIOD

From 1600 UTC 14 JUL 2021 To 1559 UTC 6 OCT 2021

3. RADIO NAVIGATION AIDS INFORMATION

Name of Station (VAR) (VOR: Declination)	ID	Frequency (CH)	Coordinates	ELEV DME Antenna (ft AMSL)
JEJU VORTAC (7° W)	CJU	116.1 MHz (CH 108X)	33°23'05"N 126°37'27"E	2 800

4. REMARKS

(1) En-route

- The use of ATS routes (B576 : IPDAS-CJU-ATOTI, A586 : GOSBO-CJU-RUGMA, A595 : CJU-SAMDO) can only be used under the following condition.
 - a. RNAV capable ACFT can fly those routes.
 - b. Except RNAV capable ACFT, alternative routes will be advised by ATC.
- Radar service will be provided by Incheon ACC.

(2) Flight procedure

- During the replacement period, some flight procedures of RKPC will not be available as follows.

	RWY	Procedure	AIP Page
SID	07	IPDAS 4K, MAKET 4K, CJU 4K, TAMNA 2K	RKPC AD CHART 2-13
	25	CJU 2L	RKPC AD CHART 2-15

- ACFT shall advise ATC (Jeju APP/TWR) for alternatives.
- Radar service will be provided by Jeju APP.

(3) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

