

TEL : 82-32-880-0256
FAX : 82-32-889-5902
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : <http://ais.casa.go.kr>

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 12/22
7 APR 2022

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

**TEMPORARY SUSPENSION OF THE TERMINAL DOPPLER WEATHER RADAR
AT INCHEON INTL AIRPORT**

1. INTRODUCTION

- (1) This AIP SUP refers to the 3rd paragraph on the page of GEN 3.5-1 in the AIP.
- (2) The operation of the TDWR (Terminal Doppler Weather Radar) at Incheon INTL Airport will be temporarily suspended due to replacement work.

2. PERIOD

From 0000 UTC 9 MAY 2022 To 0000 UTC 16 AUG 2022

3. DETAILED INFORMATION

- (1) During the suspension of the TDWR operation, the wind shear alert information remains available by the LLWAS (Low-Level Wind shear Alert System); the coverage of the LLWAS is all of the RWYs and 1(up to 2) NM from the end of each RWY.
- (2) After the replacement is completed, the TDWR services will be resumed by the new TDWR.
- (3) Any change to the contents of this page will be notified by both NOTAM and the website at global.amo.go.kr.