

TEL : 82-32-880-0256
 FAX : 82-32-889-5902
 AFS : RKRRYNYX
 E-mail : aisd@korea.kr
 Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
 11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 27/22
25 AUG 2022

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

RWY 15R/33L AND TWY CLOSED DUE TO CONSTRUCTION

1. INTRODUCTION

- (1) RWY 15R/33L will be closed due to pavement construction.
- (2) TWYs R4, R9, R10 and some of ACFT stands in apron 2 will be closed due to apron construction.

2. CLOSED AREAS & PERIOD (See the diagram)


Closed Areas			Period(UTC)
A	A1	RWY 15R/33L between TWY K and L ※ No effect on TWY K operation.	From 1600 UTC 05 SEP 2022 To 1600 UTC 28 DEC 2022
		TWY B between TWY A16 and A19 ※ No effect on TWY A16 operation.	
	A2	RWY 15R/33L between TWY G and K ※ No effect on TWY G and K operation.	
		TWY B between TWY A4 and A15 ※ No effect on TWY A4 and A15 operation.	
		Rapid exit TWY B2, B3, B5, B6	
		TWY C between TWY C2 and C4	
		Rapid exit TWY C2, C4	
B		TWY M10 between TWY M and R4 ※ No effect on TWY M operation.	
		TWY R4 between TWY M10 and M11 ※ No effect on TWY M11 operation.	
		TWY R9 between TWY R4 and ACFT stand NR. 306	
		TWY R10 between TWY R4 and ACFT stand NR. 306	
		ACFT stands NR. 306, 307, 308, 309, 310, 311, 312, 313, 314, 315	

3. REMARKS

- (1) RWY 15R/33L and TWYs will be closed as shown in the diagram.
- (2) Unserviceability lights and frangible barriers will be installed on the closed area.
- (3) All lights including RWY center line lights, RWY edge lights, RWY touchdown lights, Approach lighting system for RWY 15R/33L will be unserviceable.
- (4) Some parts of standard taxi routes(AIP RKS I AD CHART 2-6, 2-7, 2-8, 2-9) and low visibility procedure (AIP RKS I AD 2-29, 2-30, 2-31, 2-32) will be temporarily changed due to the construction.
- (5) Standard taxi routes of the closed area may be changed by the ATC instruction.
- (6) TWY center line lights, TWY edge lights, Stop bar lights and TWY guidance sign for the closed area will not be operated.
- (7) Works by equipment and vehicles will be conducted in the working area as shown in the diagram.
- (8) Any change to the contents of these pages will be notified by NOTAM.


(AIRAC AIP SUP 14/22 is hereby superseded from 1600 UTC 05 SEP 2022)

4. DIAGRAMS




Temporary Taxi Routes

Arrival for RWY 15L/R, 16L/R




Temporary Taxi Routes

Departure for 15L/R, 16L/R



Temporary Taxi Routes

Arrival for RWY 33L/R, 34L/R



Temporary Taxi Routes

Departure for RWY 33L/R, 34L/R

