TEL: 82-32-880-0256 FAX: 82-32-889-5902 AFS: RKRRYNYX

E-mail: aisd@korea.kr Web: http://ais.casa.go.kr

# REPUBLIC OF KOREA

# Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC AIP

Supplement 18/22

17 NOV 2022

GEN: NIL

**ENR: NIL** 

A D: SEOUL/Incheon INTL(RKSI)

### RWY 15R/33L AND TWYs CLOSED DUE TO CONSTRUCTION

#### 1. INTRODUCTION

- (1) RWY 15R/33L will be closed due to pavement construction.
- (2) Some of ACFT stands in apron 2 will be closed due to apron construction.

## 2. CLOSED AREAS & PERIOD (See the diagram)

Closed Areas			Period(UTC)
Α	A1	RWY 15R/33L between TWY K and L	From 1600 UTC 28 DEC 2022 To 1600 UTC 25 JAN 2023
		TWY B between TWY A16 and A19	
	A2	RWY 15R/33L between TWY G and K  ** No effect on TWY G and K operation.	
		TWY B between TWY A8 and A15 * No effect on TWY A8 and A15 operation.	
		Rapid exit TWY B2, B3, B5, B6	
		TWY C between TWY C2 and C4	
		Rapid exit TWY C2, C4	
В		ACFT stands NR. 306, 307, 308, 309, 310, 311, 312, 313, 314, 315	

#### 3. REMARKS

- (1) RWY 15R/33L and TWYs will be closed as shown in the diagram.
- (2) Unserviceability lights and frangible barriers will be installed on the closed area.
- (3) All lights including RWY center line lights, RWY edge lights, RWY touchdown lights, Approach lighting system for RWY 15R/33L will be unserviceable.
- (4) Some parts of standard taxi routes(AIP RKSI AD CHART 2-6, 2-7, 2-8, 2-9) and low visibility procedure (AIP RKSI AD 2-29, 2-30, 2-31, 2-32) will be temporarily changed due to the construction.
- (5) Standard taxi routes of the closed area may be changed by the ATC instruction.
- (6) TWY center line lights, TWY edge lights, Stop bar lights and TWY guidance sign for the closed area will not be operated.
- (7) Works by equipment and vehicles will be conducted in the working area as shown in the diagram.
- (8) Any change to the contents of these pages will be notified by NOTAM.









