

TEL : 82-32-880-0256
FAX : 82-32-889-5902
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 19/22
17 NOV 2022

GEN : NIL

ENR : NIL

A D : SEOUL/Gimpo INTL(RKSS)

OPERATIONAL RESTRICTIONS

1. INTRODUCTION

Some part of P5, some part of N1, P6, N3, N4, N5, aprons(ACFT stands NR. 211 to 214, 233 to 237, 301 to 303) and run-up pad at Gimpo INTL Airport will be closed as follows due to pavement construction.

2. PERIOD

From 1400 UTC 29 DEC 2022 To 1400 UTC 11 JUN 2023

3. WORKING AREAS (See the diagram below)

Location			Period	Working Hours
Some part of P5 Some part of N1, P6, N3, N4, N5	ACFT stands NR. 211 to 214, 233 to 237, 301 to 303	Run-up Pad	From 1400 UTC 29 DEC 2022 To 1400 UTC 11 JUN 2023	H24

4. REMARKS


(1) Safety fences and lights will be installed to indicate the working area.

(2) Departure procedures






ACFT Stands	Lead-out Procedures	Phraseology
NR. 38 ~ 39 NR. 304 ~ 307	All ACFT shall be pushed back to face Southeast on N2	Pushback approved to TWY N2.

(3) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM



6. LOW VISIBILITY PROCEDURE

Arrival	
Departure	
14R/L	
	
32R/L	