

TEL : 82-32-880-0256
FAX : 82-32-889-5902
AFS : RRRYNYX
E-mail : aisd@korea.kr
Web : http://ais.casa.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 1/23
12 JAN 2023

GEN : NIL

ENR : NIL

A D : ULJIN/Uljin(RKTL)

UNSERVICEABILITY OF UJN VORTAC

1. INTRODUCTION

The VORTAC(UJN) at Uljin Airport will be unserviceable due to VOR/DME replacement.

2. PERIOD

From 1600 UTC 22 FEB 2023 To 1600 UTC 9 AUG 2023

3. RADIO NAVIGATION AND LANDING AIDS INFO

Type of Aid	ID	Frequency	Position of Transmitting Antenna Coordinates	AIP Page
VORTAC	UJN	115.3 MHz (CH 100X)	36°46'35.2"N 129°27'26.9"E (VORTAC)	RKTL AD 2-7

4. REMARKS

(1) During the replacement period, some flight procedures of RKTL will not be available as follows.

	RWY	Procedure	AIP Page
SID	17	NOBUT 2S / LOSTO 2S	RKTL AD CHART 2-8
		LOSTO 6S	RKTL AD CHART 2-9
	35	NOBUT 2N / LOSTO 2N	RKTL AD CHART 2-11
		LOSTO 1A	RKTL AD CHART 2-12
STAR	35	RADAR 1A	RKTL AD CHART 2-13
		NOBUT 2D / LOSTO 2D	RKTL AD CHART 2-15
		NOBUT 2C / LOSTO 2C	RKTL AD CHART 2-17
Instrument Approach	17	ILS Y or LOC Y RWY 17	RKTL AD CHART 2-19
		VOR RWY 17	RKTL AD CHART 2-21
	35	ILS Y or LOC Y RWY 35	RKTL AD CHART 2-23
		VOR RWY 35	RKTL AD CHART 2-25

(2) During the replacement period, flight procedures of RKTL will be available radar vector.

(3) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

