

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : https://aim.koca.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 3/24
11 JAN 2024

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

RWY 15L/33R AND TWYs CLOSED DUE TO CONSTRUCTION

1. INTRODUCTION

- (1) RWY 15L/33R will be closed due to pavement construction.
- (2) Some parts of TWY C will be closed due to pavement construction.

2. CLOSED AREAS & PERIOD (See the diagram)


Closed Areas		Period(UTC)
A	RWY 15L/33R between TWY J and K ※ No effect on TWY J and K operation.	From 1600 UTC 1 NOV 2023 To 1600 UTC 12 JUN 2024
	TWY C between TWY J and K	
	Rapid exit TWY C1, C2, C4, C5	
	Rapid exit TWY D1, D6	
B	RWY 15L/33R below TWY J	
	TWY G between TWY C and D ※ No effect on TWY C and D operation.	
C	RWY 15L/33R between TWY K and TWY L ※ No effect on TWY K and L operation.	From 1600 UTC 21 FEB 2024 To 1600 UTC 12 JUN 2024

3. REMARKS

- (1) RWY 15L/33R and TWYs will be closed as shown in the diagrams.
- (2) Unserviceability lights and frangible barriers will be installed on the closed areas.
- (3) All lights including RWY centerline lights, RWY edge lights, RWY touchdown lights, Approach lighting system for RWY 15L/33R will be unserviceable.
- (4) Some parts of standard taxi routes(AIP RKSI AD CHART 2-6, 2-7, 2-8, 2-9) and low visibility procedures (AIP RKSI AD 2-29, 2-30, 2-31, 2-32) will be temporarily changed due to the construction.
- (5) Temporary taxi routes may be changed by the ATC instruction.
- (6) TWY centerline lights, TWY edge lights, Stop bar lights and Taxiway guidance sign for the closed areas will not be operated.
- (7) Works by equipment and vehicles will be conducted in the working area as shown in the diagrams.
- (8) Closed runway lighting is operated From 0800 To 2300 UTC at the thresholds of RWY 33R.
- (9) Any change to the contents of these pages will be notified by NOTAM.


(AIRAC AIP SUP 25/23 is hereby superseded)

4. DIAGRAMS




Temporary Taxi Routes (AIP RKSI AD CHART 2-7, 2-9 and AD 2-29)

Arrival for RWY 15L/R, 16L/R




Temporary Taxi Routes
(AIP RKSI AD CHART 2-6, 2-8 and AD 2-32)

Departure for 15L/R, 16L/R



Temporary Taxi Routes
(AIP RKSI AD CHART 2-7, 2-9 and AD 2-30)

Arrival for RWY 33L/R, 34L/R



Temporary Taxi Routes
(AIP RKSI AD CHART 2-6, 2-8 and AD 2-31)

Departure for RWY 33L/R, 34L/R

