

TEL : 82-53-668-0286  
FAX : 82-53-668-0277  
AFS : RKRRYNYX  
E-mail : aisd@korea.kr  
Web : <https://aim.koca.go.kr>

**REPUBLIC OF KOREA**  
**Ministry of Land, Infrastructure and Transport**  
**Office of Civil Aviation**  
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

**AIRAC**  
**AIP**  
**Supplement 18/24**  
**4 APR 2024**

**GEN : NIL**

**ENR : NIL**

**A D : SEOUL/Gimpo INTL(RKSS)**

## **OPERATIONAL RESTRICTIONS**

### **1. INTRODUCTION**

Operational restrictions due to a TWY repavement construction and a TCLL(Taxiway center line light) replacement work.

### **2. PERIOD**

From 1400 UTC 16 MAY 2024 To 2000 UTC 14 JUN 2024

### **3. WORKING AREAS** (See the diagram below)

<b>Area</b>	<b>Location</b>	<b>Period</b>	<b>Working Hours(UTC)</b>
①	TWY P	16 MAY 2024 ~ 14 JUN 2024	1400 ~ 2000 Daily
②	TWY B1	16 MAY 2024 ~ 14 JUN 2024	1400 ~ 2000 Daily

### **4. REMARKS**

- (1) TWY P, B1 under work will be closed From 1400 UTC To 2000 UTC daily during working period.
- (2) TCLL(Taxiway center line light) for TWY P(area ①), TWY B1(area ②) is unserviceable From 1400 UTC 16 MAY 2024 To 2000 UTC 14 JUN 2024 irrespective of working hours.
- (3) If low visibility procedures operated in case of less than RVR 400 m, TWY P(area ①) will be closed.
- (4) If low visibility procedures operated in case of less than RVR 400 m, follow me car service will be provided for aircraft using TWY B1(area ②).
- (5) RWY 32L take-off weather minimum will be changed to RVR 400 m.
- (6) After termination of the daily scheduled flight, work will begin.
- (7) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

< RWY 14R/32L and 14L/32R and exit TWY >

