

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : https://aim.koca.go.kr

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC
AIP
Supplement 21/24
2 MAY 2024

GEN : NIL

ENR : NIL

A D : SEOUL/Gimpo INTL(RKSS)

OPERATIONAL RESTRICTIONS

1. INTRODUCTION

Operational restrictions due to a TWY repavement construction and a TCLL(Taxiway center line light), REDL(Runway edge light) replacement work.


2. PERIOD

From 1400 UTC 1 JUL 2024 To 2000 UTC 11 OCT 2024

3. WORKING AREA (See the diagram below)

Diagram

- ① TCLL, REDL for TWY C2 unserviceable.
- A distance of construction is 230 m.



Area	Location	Period	Working Hours(UTC)
①	TWY C2	1 JUL 2024 ~ 11 OCT 2024	1400 ~ 2000 Daily

4. REMARKS

- (1) TWY C2 under work will be closed From 1400 UTC To 2000 UTC daily during working period.
- (2) TCLL(Taxiway center line light), REDL(Runway edge light) for TWY C2(area ①) is unserviceable From 1400 UTC 1 JUL 2024 To 2000 UTC 11 OCT 2024 irrespective of working hours.
- (3) If low visibility procedures operated in case of less than RVR 400 m, all arrival ACFT using RWY 14R shall vacate via B1 as shown in the diagram.
- (4) After termination of the daily scheduled flight, work will begin.
- (5) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

Temporary Taxi Routes
(AIP RKSS AD 2-16)

Arrival for RWY 14R in case of less than RVR 400 m

