TEL: 82-53-668-0286 FAX: 82-53-668-0277 AFS: RKRRYNYX

E-mail: aisd@korea.kr Web: https://aim.koca.go.kr

REPUBLIC OF KOREA

Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC AIP

Supplement 44/24 22 AUG 2024

GEN: NIL

ENR: NIL

A D: SEOUL/Gimpo INTL(RKSS)

OPERATIONAL RESTRICTIONS

(Effective: 1600UTC 2 OCT 2024)


1. INTRODUCTION

Operational restrictions due to a TWY repavement construction and a TCLL(Taxiway center line light), REDL(Runway edge light) replacement work.

2. PERIOD

From 1400 UTC 12 OCT 2024 To 2000 UTC 25 OCT 2024

3. WORKING AREA (See the diagram below)



Area	Location	Period	Working Hours(UTC)
1)	TWY C2	12 OCT 2024 ~ 25 OCT 2024	1400 ~ 2000 Daily

4. REMARKS

- (1) TWY C2 under work will be closed from 1400 UTC to 2000 UTC daily during working period.
- (2) TCLL(Taxiway center line light), REDL(Runway edge light) for TWY C2(area ①) is unserviceable From 1400 UTC 12 OCT 2024 To 2000 UTC 25 OCT 2024 irrespective of working hours.
- (3) If low visibility procedures operated in case of less than RVR 400 m, all arrival ACFT using RWY 14R shall vacate via B1 as shown in the diagram.
- (4) After termination of the daily scheduled flight, work will begin.
- (5) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAM

