TEL: 82-53-668-0286 FAX: 82-53-668-0277 AFS: RKRRYNYX

E-mail: aisd@korea.kr Web: https://aim.koca.go.kr

# REPUBLIC OF KOREA

# Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC AIP

Supplement 16/25

6 FEB 2025

**GEN: NIL** 

**ENR: NIL** 

A D: SEOUL/Incheon INTL(RKSI)

# RWY 15L/33R AND TWYs CLOSED DUE TO CONSTRUCTION

(Effective: 1600UTC 19 MAR 2025)

#### 1. INTRODUCTION

- (1) RWY 15L/33R will be closed due to pavement construction.
- (2) Some parts of TWY D will be closed due to pavement construction.


#### 2. CLOSED AREAS & PERIOD (See the diagrams)

Closed Areas		Period(UTC)
A	RWY 15L/33R between TWY J and L  No effect on TWY J and TWY L operation.  Rapid exit TWY C1, C2, C4, C5  Rapid exit TWY D1, D6  TWY K between RWY 15R/33L and TWY D  No effect on RWY 15R/33L operation.  TWY C between TWY K and TWY L  No effect on TWY L operation.  TWY D between TWY D4 and TWY L  No effect on TWY D4 and TWY L	From 1600 UTC 19 MAR 2025 To 1600 UTC 2 OCT 2025

#### 3. REMARKS

- (1) RWY 15L/33R and TWYs will be closed as shown in the diagrams.
- (2) Unserviceability lights and frangible barriers will be installed on the closed area.
- (3) All lights including RWY centerline lights, RWY edge lights, RWY touchdown lights, Approach lighting system for RWY 15L/33R will be unserviceable.
- (4) Some parts of standard taxi routes(AIP RKSI AD CHART 2-6, 2-7, 2-8, 2-9) and low visibility procedure (AIP RKSI AD 2-29, 2-30, 2-31, 2-32) will be temporarily changed due to the construction.
- (5) Temporary taxi routes may be changed by the ATC instruction.
- (6) TWY centerline lights, TWY edge lights, Stop bar lights and Taxiway guidance sign for the closed area will not be operated.
- (7) Works by equipment and vehicles will be conducted in the working area as shown in the diagrams.
- (8) Closed runway lighting is operated From 0800 To 2300 UTC at the thresholds of RWY 33R.
- (9) Any change to the contents of these pages will be notified by NOTAM.


(AIRAC AIP SUP 69/24 is hereby superseded)



## **Temporary Taxi Routes**


(AIP RKSI AD CHART 2-7, 2-9 and AD 2-29)

Arrival for RWY 15L/R, 16L/R



# Temporary Taxi Routes (AIP RKSI AD CHART 2-6, 2-8 and AD 2-32)


Departure for 15L/R, 16L/R



## **Temporary Taxi Routes**

(AIP RKSI AD CHART 2-7, 2-9 and AD 2-30)

Arrival for RWY 33L/R, 34L/R



## **Temporary Taxi Routes**

(AIP RKSI AD CHART 2-6, 2-8 and AD 2-31)

Departure for RWY 33L/R, 34L/R

