

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : <https://aim.koca.go.kr>

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 35/25
3 APR 2025

GEN : NIL

ENR : NIL

A D : SEOUL/Incheon INTL(RKSI)

TEMPORARY OBSTACLES ERECTED

1. INTRODUCTION

The obstacles will be installed at the east side of RWY 16L/34R of Incheon INTL Airport.

※ The obstacles are located about 780 m to the east from the centerline of RWY 16L/34R.

2. PERIOD

From 2200 UTC 2 APR 2025 To 0900 UTC 14 JUN 2025

3. WORKING AREAS (※ See the diagrams)

| NR. | Position | | OBST Type | Height | | Remarks |
|-----|-----------------|------------------|----------------------------|--------|------|-----------------------|
| | | | | AGL | AMSL | |
| ① | 37°28'50.8062"N | 126°25'07.5302"E | Cranes Drilling machine | 42 m | 46 m | Marked and Lighted |
| ② | 37°28'51.6972"N | 126°25'09.1066"E | | 42 m | 46 m | |
| ③ | 37°28'48.9590"N | 126°25'12.6085"E | | 42 m | 46 m | |
| ④ | 37°28'47.8652"N | 126°25'10.6760"E | | 42 m | 46 m | |
| ⑤ | 37°28'47.9501"N | 126°25'10.0697"E | | 42 m | 46 m | |

4. REMARKS

- (1) Works by equipment & vehicles will be conducted in the area as shown in diagrams.
- (2) Equipment and vehicles do not penetrate obstacle limitation surfaces.
- (3) Lights will be installed on the top of the every crane.
- (4) Any change to the contents of these pages will be notified by NOTAM.

5. DIAGRAMS

