

TEL : 82-53-668-0286
FAX : 82-53-668-0277
AFS : RKRRYNYX
E-mail : aisd@korea.kr
Web : <https://aim.koca.go.kr>

REPUBLIC OF KOREA
Ministry of Land, Infrastructure and Transport
Office of Civil Aviation
11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP
Supplement 38/25
3 APR 2025

GEN : NIL

ENR : NIL

A D : JEJU/Jeongseok(RKPD)

UNSERVICEABILITY OF LOC FOR RWY 01

1. INTRODUCTION

The LOC for RWY 01 at Jeongseok Aerodrome will be unserviceable due to maintenance.

2. PERIOD

From 2330 UTC 2 APR 2025 To 0830 UTC 31 JUL 2025

3. RADIO NAVIGATION AND LANDING AIDS INFO

Type of aid, CAT of ILS/MSL	ID	Frequency	Position of Transmitting Antenna Coordinates
LOC 01	IJDG	108.3 MHz	33°24'22.7"N 126°42'41.2"E
GP 01	-	334.1 MHz	33°23'07.5"N 126°42'46.3"E
DME 01	-	981 MHz (CH 20X)	33°23'07.8"N 126°42'46.5"E

4. REMARKS

(1) During the replacement period, some flight procedures of RKPD will not be available as follows.

	RWY	Procedures	AIP Page
INSTR APCH	01	ILS RWY 01	RKPD AD CHART 2-15
		LOC RWY 01	RKPD AD CHART 2-16

(2) Obstacles do not penetrate any obstacle limitation surfaces of RKPD.

(3) Any change to the contents of this page will be notified by NOTAM.