TEL: 82-53-668-0286 FAX: 82-53-668-0277 AFS: RKRRYNYX

E-mail: aisd@korea.kr Web: https://aim.koca.go.kr

# REPUBLIC OF KOREA

## Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIRAC AIP

Supplement 47/25

1 MAY 2025

GEN: NIL

**ENR: NIL** 

A D: JEJU/Jeju INTL(RKPC)

### TEMPORARY OBSTACLE ERECTED

(Effective: 1600UTC 11 JUN 2025)

#### 1. INTRODUCTION

The obstacle(tower crane) will be installed at the south side of RWY 07/25 of Jeju INTL Airport. \*\* The obstacle is located about 641 m to the south from the centerline of RWY 07/25.

#### 2. PERIOD

From 1600 UTC 11 JUN 2025 To 1600 UTC 21 JAN 2026

### 3. OBST INFORMATION (See the diagram)

	NR.	Position		OBST Type	Height		Downada
					AGL	AMSL	Remarks
	1	33°30'14.48"N	126°29'22.66"E	Tower Crane	121.39 m	149.89 m	Marked and Lighted

#### 4. REMARKS

- (1) During the period, the OCA(H) of some instrument approach procedures for Jeju INTL Airport will be changed (See AIRAC AIP SUP 48/25).
- (2) The crane penetrates the transitional surface of RKPC.
- (3) Tower crane turns on its axis (Radius Max 30 m).
- (4) Lights will be installed in the upper part of the tower crane.
- (5) Any change to the contents of these pages will be notified by NOTAM.

# 5. DIAGRAM

