TEL: 82-53-668-0286 FAX: 82-53-668-0277

AFS: RKRRYNYX
E-mail: aisd@korea.kr
Web: https://aim.koca.go.kr

### REPUBLIC OF KOREA

## Ministry of Land, Infrastructure and Transport Office of Civil Aviation

11, Doum 6-ro, Sejong-si, 30103, Republic of Korea

AIP

Supplement 71/25

21 AUG 2025

GEN: NIL

**ENR: NIL** 

A D: MUAN/Muan INTL(RKJB)

#### TEMPORARY SECURITY FENCE AND TEMPORARY OBSTACLES ERECTED

#### 1. INTRODUCTION

Temporary security fence & lights and CCTVs will be installed on the area as follows.

#### 2. PERIOD

From 1500 UTC 20 AUG 2025 To 1500 UTC 31 OCT 2025

#### 3. OBST INFORMATION

NR.	OBST Type	Position	Height	
			AGL	AMSL
1	Security Fence	35°00'19.45"N 126°22'51.20"E	3.3 m	19.27 m
2	Security Fence	35°00'19.68"N 126°23'07.55"E		
3	Security Light	35°00'19.38"N 126°22'52.75"E	5.0 m	19.65 m
4	Security Light	35°00'19.40"N 126°22'54.53"E		
5	Security Light	35°00'19.45"N 126°22'58.17"E	5.0 m	20.97 m
6	Security Light	35°00'19.48"N 126°23'00.03"E		
7	Security Light	35°00'19.53"N 126°23'03.69"E	5.0 m	19.87 m
8	Security Light	35°00'19.56"N 126°23'05.51"E		
9	CCTV	35°00'19.36"N 126°22'51.34"E		
10	CCTV	35°00'19.43"N 126°22'56.30"E	7.0 m	22.40 m
11)	CCTV	35°00'19.51"N 126°23'01.88"E		

#### 4. REMARKS

- (1) During working period, pilots should exercise caution and follow ATC's instruction.
- (2) Work by equipments & vehicles will be conducted in the area as shown in AIRAC AIP SUP 72/25 (CONSTRUCTION WORK FOR RUNWAY EXTENSION).
  - (Until the AIRAC AIP SUP 72/25 becomes effective, working area information will be provided by NOTAM)
- (3) Temporary security fence & lights and CCTVs will be installed as shown in the diagram.
- (4) Temporary security fence & lights and CCTVs do not penetrate obstacle limitation surface.
- (5) Any change to the contents of these pages will be notified by NOTAM.

(AIP SUP 22/25 is hereby superseded)

# 5. DIAGRAM Displaced temporary Security Fence Displaced threshold 300.0m Security Fence Security Light REMARK CCTV 3~8